2010 Structure Summary Report

Overall Unit and Item Ratings

Butte County Public Works

Big Chico Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
Α	Vegetation & Obstructions	А
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	N
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α

Ν

Safety

Lindo Channel Control Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
	Culverts: Breaks / Holes / Cracks	Α
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	Α
	Electric Gate Operators	N
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	М
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	Α
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	N

2010 Structure Summary Report

Overall Unit and Item Ratings

Butte County Public Works (cont.)

Lindo Channel Diversion Weir

Overall Unit Rating	Item Rating	
A	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	М
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	Α
	Safety	N

Unit Cover Sheet

2010 Structure Inspection Results

Butte County Public Works

Structure	
Big Chico Creek Diversion Structure	

Structure Rating	Α
Date of Inspection	9/3/2010
DWR Inspector	Bob Duffey
Accompanied By	Dave Herfi Butte Co.

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure		09/03/2010 09/03/2010	Bob Duffey

LMR No.	Levee	Mile End	Category	Item	Rating ** Location *	Action/Comment	GPS Latitude/Longitude	Issue No.
1			Structures	Photo Documentation			39.763308 ° 39.763308 ° -121.791903 ° -121.791903 °	
2			Structures	Vegetation & Obstructions	Α		39.762678 ° 39.762678 ° -121.792338 ° -121.792338 °	
3	0.00	0.00	Structures	Shoaling / Sedimentation	Α		39.763308 ° 39.763308 ° -121.791903 °	
4	0.00	0.00	Structures	Erosion / Bank Caving	Α		39.763308 ° 39.763308 ° -121.791903 °	
5	0.00	0.00	Structures	Revetments	Α		39.763308 ° 39.763308 ° -121.791903 °	
6	0.00	0.00	Structures	Encroachments	Α		39.763308 ° 39.763308 ° -121.791903 ° -121.791903 °	
7	0.00	0.00	Structures	Culverts: Inlets / Outlets	N		39.763308 ° 39.763308 ° -121.791903 ° -121.791903 °	
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks	N		39.763308 ° 39.763308 ° -121.791903 ° -121.791903 °	
9	0.00	0.00	Structures	Metal Pipes	N		39.763308° 39.763308° -121.791903°-121.791903°	
10	0.00	0.00	Structures	Trash Racks	N		39.763308 ° 39.763308 ° -121.791903 °	
11	0.00	0.00	Structures	Flap Gates	N		39.763308 ° 39.763308 ° -121.791903 ° -121.791903 °	
12	0.00	0.00	Structures	Sluice/Slide Gates	Α		39.763308 ° 39.763308 ° -121.791903 ° -121.791903 °	
13	0.00	0.00	Structures	Electric Gate Operators	N		39.763308 ° 39.763308 ° -121.791903 °	
14	0.00	0.00	Structures	Manual Gate Operators	Α		39.763308 ° 39.763308 ° -121.791903 °	
15	0.00	0.00	Structures	Concrete Surfaces	Α		39.763308 ° 39.763308 ° -121.791903 °	
16	0.00	0.00	Structures	Concrete Tilting / Settlement	Α		39.763308 ° 39.763308 ° -121.791903 °	
17	0.00	0.00	Structures	Concrete Foundations	Α		39.763308 ° 39.763308 ° -121.791903 °	

* Location

LS : Land Side

WS : Water Side

CR : Crown

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure		09/03/2010 09/03/2010	Bob Duffey

LMR	Levee					evee Mile							Location Rating Rating Action/Comment		GPS Latitude/Longitude		
No.	Start	End	Category	Item	ing * ation	Action/Comment	Start	End ^항	Issue No.								
18	0.00	0.00	Structures	Security Fencing	N		39.763308 ° -121.791903 ° -1	39.763308 ° 21.791903 °	17								
19	0.00	0.00	Structures	Closure Structures	Α		39.763308 ° -121.791903 ° -1	39.763308 ° 21.791903 °	18								
20	0.00	0.00	Structures	Trash Rakes	N		39.763308 ° -121.791903 ° -1	39.763308 ° 21.791903 °	19								
21	0.00	0.00	Structures	Other Metallic Items	N		39.763308 ° -121.791903 ° -1	39.763308 ° 21.791903 °	20								
22	0.00	0.00	Structures	Monolith Joints	Α		39.763308 ° -121.791903 ° -1	39.763308 ° 21.791903 °	21								
23	0.00	0.00	Structures	Safety	N		39.763308 ° -121.791903 ° -1	39.763308 ° 21.791903 °	22								

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Page 3 of 3

Flood Control Project Maintenance Levee Inspections

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure		09/03/2010 09/03/2010	Bob Duffey

Levee Mile Report Line	1				
Start Levee Mile					
End Levee Mile					
Location					
Category	Structures				
Item	Photo Documentation				
View of the structure.					
rduffey_t_20100914_081.jpg					

Levee Mile Report Line	2				
Start Levee Mile					
End Levee Mile					
Location					
Category	Structures				
Item	Vegetation & Obstructions				
View of the upstream side of the structure.					

rduffey_t_20100914_079.jpg

Levee Mile Report Line	2			
Start Levee Mile				
End Levee Mile				
Location				
Category	Structures			
Item	Vegetation & Obstructions			
View of the discharge side of the structure.				

rduffey_t_20100914_080.jpg







A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Unit Cover Sheet

2010 Structure Inspection Results

Butte County Public Works

Structure	
Lindo Channel Control Structure	

Structure Rating	Α
Date of Inspection	9/3/2010
DWR Inspector	Bob Duffey
Accompanied By	Dave Herfi Butte Co.

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Control Structure		09/03/2010 09/03/2010	Bob Duffey

LMR No.	Levee	Mile End	Category	Item	Rating ** Location *	Action/Comment	GPS Latitude/Longitude Start End	Issue No.
1			Structures	Photo Documentation			39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	Y 23
2			Structures	Vegetation & Obstructions	Α		39.761517 ° 39.761517 ° -121.797263 ° -121.797263 °	Y 1
3	0.00	0.00	Structures	Shoaling / Sedimentation	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	2
4	0.00	0.00	Structures	Erosion / Bank Caving	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	3
5	0.00	0.00	Structures	Revetments	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	4
6	0.00	0.00	Structures	Encroachments	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	5
7	0.00	0.00	Structures	Culverts: Inlets / Outlets	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	6
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	7
9	0.00	0.00	Structures	Metal Pipes	N		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	8
10	0.00	0.00	Structures	Trash Racks	N		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	9
11	0.00	0.00	Structures	Flap Gates	N		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	10
12	0.00	0.00	Structures	Sluice/Slide Gates	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	11
13	0.00	0.00	Structures	Electric Gate Operators	N		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	12
14	0.00	0.00	Structures	Manual Gate Operators	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	13
15	0.00	0.00	Structures	Concrete Surfaces	Α		39.761520 ° 39.761520 ° -121.797265 ° -121.797265 °	14
16	0.00	0.00	Structures	Concrete Tilting / Settlement	М		39.761520 ° 39.761520 ° -121.797265 °	15
17	0.00	0.00	Structures	Concrete Foundations	Α		39.761520 ° 39.761520 ° -121.797265 °	16

* Location

LS : Land Side

WS : Water Side

CR : Crown

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Control Structure		09/03/2010 09/03/2010	Bob Duffey

LMR	Levee	Mile	0-4	H	Rating ** Location	Action/Comment	GPS Latitude/Longi	tude 🚆	Issue No.
No.	Start	End	Category	Item	ing * ation		Start End	j §	No.
18	0.00	0.00	Structures	Security Fencing	Α		39.761520 ° 39.761 -121.797265 ° -121.797		17
19	0.00	0.00	Structures	Closure Structures	Α		39.761520 ° 39.761 -121.797265 ° -121.797		18
20	0.00	0.00	Structures	Trash Rakes	N		39.761520 ° 39.761 -121.797265 ° -121.797		19
21	0.00	0.00	Structures	Other Metallic Items	N		39.761520 ° 39.761 -121.797265 ° -121.797		20
22	0.00	0.00	Structures	Monolith Joints	А		39.761520 ° 39.761 -121.797265 ° -121.797		21
23	0.00	0.00	Structures	Safety	N		39.761520 ° 39.761 -121.797265 ° -121.797		22

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Control Structure		09/03/2010 09/03/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	
End Levee Mile	
Location	
Category	Structures
Item	Photo Documentation
View of the structure.	
rduffey_t_20100914_084.jpo	3

Levee Mile Report Line	2				
Start Levee Mile					
End Levee Mile					
Location					
Category	Structures				
Item	Vegetation & Obstructions				
View of the upstream side of structure.					
rduffey_t_20100914_082.jpg					

Levee Mile Report Line	2			
Start Levee Mile				
End Levee Mile				
Location				
Category	Structures			
Item	Vegetation & Obstructions			
View of the downstream side of structure.				
rduffey_t_20100914_083.jpg	9			







A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Unit Cover Sheet

2010 Structure Inspection Results

Butte County Public Works

Structure	
Lindo Channel Diversion Weir	

Structure Rating	Α
Date of Inspection	9/3/2010
DWR Inspector	Bob Duffey
Accompanied By	Dave Herfi Butte Co.

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir		09/03/2010 09/03/2010	Bob Duffey

LMR No.	Levee	Mile End	Category	Item	Rating ** Location	Action/Comment GPS Latitude/L	Longitude Photo Photo End
1	·	·	Structures	Photo Documentation		39.762012 ° 3 -121.797330 ° -12	9.762012 ° Y 23 1.797330 °
2			Structures	Vegetation & Obstructions	Α	39.762010° 3 -121.797328°-12	9.762010 ° Y 1 1.797328 °
3	0.00	0.00	Structures	Shoaling / Sedimentation	Α	39.762012° 3 -121.797330°-12	
4	0.00	0.00	Structures	Erosion / Bank Caving	Α	39.762012° 3 -121.797330°-12	• · · • - • · -
5	0.00	0.00	Structures	Revetments	Α	39.762012° 3 -121.797330°-12	
6	0.00	0.00	Structures	Encroachments	М	39.762012° 3 -121.797330°-12	
7	0.00	0.00	Structures	Culverts: Inlets / Outlets	N	39.762012° 3 -121.797330°-12	
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks	N	39.762012° 3 -121.797330°-12	
9	0.00	0.00	Structures	Metal Pipes	N	39.762012° 3 -121.797330°-12	
10	0.00	0.00	Structures	Trash Racks	N	39.762012° 3 -121.797330°-12	
11	0.00	0.00	Structures	Flap Gates	N	39.762012° 3 -121.797330°-12	
12	0.00	0.00	Structures	Sluice/Slide Gates	N	39.762012 ° 3 -121.797330 ° -12	
13	0.00	0.00	Structures	Electric Gate Operators	N	39.762012° 3 -121.797330°-12	
14	0.00	0.00	Structures	Manual Gate Operators	N	39.762012° 3 -121.797330°-12	
15	0.00	0.00	Structures	Concrete Surfaces	Α	39.762012° 3 -121.797330°-12	
16	0.00	0.00	Structures	Concrete Tilting / Settlement	Α	39.762012° 3 -121.797330°-12	
17	0.00	0.00	Structures	Concrete Foundations	Α	39.762012 ° 3 -121.797330 ° -12	

* Location

LS : Land Side

WS : Water Side

CR : Crown

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir		09/03/2010 09/03/2010	Bob Duffey

LMR	Levee	Mile	Catamani	ltana	Rating ** Location	Ral Astica (Command	GPS Latitud	GPS Latitude/Longitude	
No.	Start	End	Category	Item	ing * tion	Action/Comment	Start	End	Issue No. Photo
18	0.00	0.00	Structures	Security Fencing	Α		39.762012 ° -121.797330 °		17
19	0.00	0.00	Structures	Closure Structures	N		39.762012 ° -121.797330 °		18
20	0.00	0.00	Structures	Trash Rakes	N		39.762012 ° -121.797330 °		19
21	0.00	0.00	Structures	Other Metallic Items	N		39.762012 ° -121.797330 °		20
22	0.00	0.00	Structures	Monolith Joints	Α		39.762012 ° -121.797330 °		21
23	0.00	0.00	Structures	Safety	N		39.762012 ° -121.797330 °		22

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2010

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir		09/03/2010 09/03/2010	Bob Duffey

Levee Mile Report Line	1					
Start Levee Mile						
End Levee Mile						
Location						
Category	Structures					
Item Photo Documentation						
View of the structure.						
rduffey_t_20100914_087.jpg						

Levee Mile Report Line	2		
Start Levee Mile			
End Levee Mile			
Location			
Category	Structures		
Item	Vegetation & Obstructions		
Upstream side of the structure from the left bank			

rduffey_t_20100914_085.jpg

Levee Mile Report Line	2
Start Levee Mile	
End Levee Mile	
Location	
Category	Structures
Item	Vegetation & Obstructions

The velocity dissipaters on the downstream side of structure from the left bank.

rduffey_t_20100914_086.jpg







*Location
LS: Land Side
WS: Water Side
CR: Crown

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable